

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 07/28/2012	3. Time Prepared 1800
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Mindy Luetke, Planning Section Chief		6. Operational Period 1200, 07/26/12 – 1200, 08/2/12
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Matthew Haak		Situation Unit Aerial Field Observer	Houston, TX
8. Activity Log			
Time	Major Events		
	Operational Observation:		
0710	<ul style="list-style-type: none"> Arrived at the ICP and began printing out the daily photolog. 		
0800	<ul style="list-style-type: none"> Attended the EPA C&G meeting. 		
0900	<ul style="list-style-type: none"> Arrived at C0.4 boat launch. MP5.25 LDB observed the sheen sweep boat operating. 		
0915	<ul style="list-style-type: none"> Boat overheated and we returned to boat launch. Boat operator went to boat shed to retrieve another boat. 		
1000	<ul style="list-style-type: none"> New boat arrived and we resumed our day on the river. MP5.25 – MP5.63 LDB sheen and tar globs observed. MP5.63 LDB heavy sheen tar globs observed. Ceresco Dam debris buildup along the control point. Ceresco Dam control point sheen and tar globs observed. Large area of sheen observed above the Ceresco Control Point. Ceresco Dam boom maintenance crew observed mobilizing to perform boom maintenance. 		
11:45	<ul style="list-style-type: none"> MP5.0 – MP5.25 RDB sheen observed Removed boat and mobilized to C05 boat launch MP15.5 South Mill Pond observed sheen sweep boat operating. MP15.5 South Mill Pond observed sheen within Mill Pond. MP14.5 LDB observed sheen. 		
12:30	<ul style="list-style-type: none"> Removed boat and mobilized to E2 boat launch. Stopped at MP21.5 RDB Custer Bridge, no sheen observed. 		
13:15	<ul style="list-style-type: none"> Launched out of E2 and stopped at 30.8 and 33.0 A&B. No sheen was observed. 		
14:30	<ul style="list-style-type: none"> Launch out of E4 boat launch. Morrow Lake north cove observed the sheen sweep boat operating. Morrow Lake north cove observed sheen. 		

	<ul style="list-style-type: none">• Morrow Lake north cove observed sheen.• Morrow Lake observed the poling crew operating in the southwest end of the lake.• Morrow Lake Delta Boom E observed the sheen sweep boat operating.• Morrow Lake Delta Boom C observed boom maintenance.• MP36.25 LDB observed sheen. <p>Planning Activities:</p> <ul style="list-style-type: none">• Completed 214• Prepared and distributed Daily Situation Unit Photolog.• Continued preparation of weekly Situation Report "SitRep"• Continued updating Organizational Staffing Gantt Chart.• Assisted with the C&G and MAC Situational Update presentation.
9.	Prepared by (Name and Position) Matthew Haak, Situation Unit, USEPA-START